



End of Sale (EOS) Notice- CMP-NIC-2TX0A, CMP-NIC-2TX0S

1. Announcement Summary

This notification is to announce the end of sale of the following part numbers effective **immediately** due to a lack of supply.

CMP-NIC-2TX0A	2-port copper NIC legacy Add'l	2-Port 10/100/1000Base-T bypass interface card for Steelhead models 510, 1010, 2010, 2510, 3010, 3510 and 5010 only (configured in system)	\$895
CMP-NIC-2TX0S	2-port copper NIC legacy Spare	2-Port 10/100/1000Base-T bypass interface card for Steelhead models 510, 1010, 2010, 2510, 3010, 3510 and 5010 only (boxed spare)	\$895

2. Migration Plan

The following **already available** parts can be used to replace the parts that are End of Sale. Please note that mixing CMP-NIC-2TX0A with either CMP-NIC-2TX1A or CMP-NIC-2TX1S in the same Steelhead is only possible beginning in RiOS v5.0.

CMP-NIC-2TX1A	2-port copper NIC Add-in	2-Port 10/100/1000Base-T bypass interface card for all Steelhead models running RiOS 2.1.3 and up (configured in system)	\$895
CMP-NIC-2TX1S	2-port copper NIC Spare	2-Port 10/100/1000Base-T bypass interface card for all Steelhead models running RiOS 2.1.3 and up (boxed spare)	\$895

Any warranty replacements (RMA's) of the EOS parts will be replaced with either the above parts or the refurbished EOS parts at Riverbed's discretion.

3. Software Requirements

The CMP-NIC-2TX1 card was supported starting at these Steelhead RiOS versions: 3.0.8, 4.0.2, 4.1, and 5.0. The card is not supported by older versions of RiOS.

4. Additional Information

For additional information regarding this change, please contact Debashish Nag at 415.247.8141.